

SUBJECT: WR2 Battery Replacement Now Available

MODELS AFFECTED: WR2BATTERY

# IMPLEMENTATION DATE CODE: August 2019

## Introduction:

The Battery Replacement spare part for WR2-RFC and WR2-48 Wireless Rain Sensors is now available for order. The spare part comes with all components allowing for a quick and easy battery replacement in the field on the WR2 Wireless Rain Sensor. It includes:

- Lithium Ion CR2032 Replacement Battery
- Replacement battery cassette (cap) with replacement O-ring

The battery is pre-installed in the replacement battery cassette, requiring no pre-work for installation into a WR2 Wireless Rain Sensor.

### Product Information:

Model	Product ID
WR2BATTERY	651009S

### Interchangeability:

The WR2BATTERY replacement part will work with all WR2 Wireless Rain/Freeze Sensors.

### Special Instructions:

The WR2 Battery Replacement Cap will require a small screwdriver or coin be used for removal from a WR2 Wireless Rain Sensor. The cap was specifically designed to fit:

- The Rain Bird Rotor Tool (Item ID: Y05100)
- A Flathead screwdriver
- A Phillips head screwdriver
- A quarter or other coin